Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI	SDG: F6R18	Contract: EPW14035	Submission Group Id: 30115344		
Lab Name: Shealy Environmental Services, Inc.	Case: 45671	Client: EPA Region 6	SOW: SOM02.3		
HoldingTimes_Preservation					

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI	SDG: F6R18	Contract: EPW14035	Submission Group Id: 30115344
Lab Name: Shealy Environmental Services, Inc.	Case: 45671	Client: EPA Region 6	SOW: SOM02.3

TUNE

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI SDG: F6R18 Contract: EPW14035 Submission Group Id: 30115344

Lab Name: Shealy Environmental Services, Inc. Case: 45671 Client: EPA Region 6 SOW: SOM02.3

InitialCalibration

Method - Volatile Organics

Test Name: EXES-793

Defect Message: The following samples are associated with an initial calibration percent relative standard deviation (%RSD) outside criteria. Detects are qualified as estimated J. Use professional judgment to qualify nondetects.

Associated Samples: F6R24, F6R25, F6R26, F6R27, VBLKPE

11000 0100 0100 1010 1,1 0100,1 0100,1 0100,1 0100,1		
Bromochloromethane	VSTD005PE	
1,2,4-Trichlorobenzene	VSTD005PE	

Method - Semivolatiles

Test Name: EXES-793

Defect Message: The following samples are associated with an initial calibration percent relative standard deviation (%RSD) outside criteria. Detects are qualified as estimated J. Use professional judgment to qualify nondetects.

Associated Samples: F6R18, F6R20, F6R21, F6R23, F6R24, F6R25, F6R26, F6R27, F6R28, SBLK12

2,6-Dinitrotoluene	SSTD005NG	
2,4-Dinitrotoluene	SSTD005NG	
2,3,4,6-Tetrachlorophenol	SSTD005NG	

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQISDG: F6R18Contract: EPW14035Submission Group Id: 30115344Lab Name: Shealy Environmental Services, Inc.Case: 45671Client: EPA Region 6SOW: SOM02.3

ContinuingCalibrationVerification

Method - Volatile Organics

Test Name: EXES-1209

Defect Message: The following samples are associated with an opening or closing CCV with % Difference exceeding criteria. Detecteds are qualified as estimated J.

Nondetects are qualified as estimated UJ.

Associated Samples: F6R24, F6R25, F6R26, F6R27, VBLKPE

Chloroethane VSTD050QA

Method - Semivolatiles by SIM

Test Name: EXES-1209

Defect Message: The following samples are associated with an opening or closing CCV with % Difference exceeding criteria. Detecteds are qualified as estimated J.

Nondetects are qualified as estimated UJ.

Associated Samples: F6R23RX, F6R24RX, F6R25, F6R26RX, SBLK13, SBLK38

Associated Samples: Forestax, Forest, Forestax, Sallins		
Acenaphthylene	SSTD0.2OW	
Acenaphthene	SSTD0.2OW, SSTD0.2PC	

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI SDG: F6R18 Contract: EPW14035 Submission Group Id: 30115344

Lab Name: Shealy Environmental Services, Inc. Case: 45671 Client: EPA Region 6 SOW: SOM02.3

Blanks

Method - Volatile Organics

Test Name: EXES-1167

Defect Message: The following samples have the same tentatively identified compounds (TIC) detected as in the associated storage blank. TIC results reported in the associated storage blank exceed concentration criteria. Detects are not qualified. Nondetects are not qualified. Use professional judgement to qualify data.

Associated Samples: F6R24, F6R25, F6R26, F6R27

Unknown-01 F6R26, F6R24, F6R25, F6R27

Test Name: EXES-1174

Defect Message: The following samples were analyzed after a highly contaminated sample and have no preceding instrument blank. Detects are not qualified.

Nondetects are not qualified. Use professional judgement to qualify data.

Associated Samples: F6R24, F6R25, F6R26, F6R27, VBLKPE, VBLKSA

Associated Samples: F6R24, F6R25, F6R26, F6R27, VBLKPE, VBLKSA				
Dichlorodifluoromethane	F6R26, F6R24, VBLKSA, VBLKPE, F6R27, F6R25			
Chloromethane	VBLKSA, F6R24, F6R25, F6R26, VBLKPE, F6R27			
Vinyl chloride	F6R26, F6R24, VBLKSA, F6R27, F6R25, VBLKPE			
Bromomethane	F6R25, F6R26, F6R24, VBLKPE, F6R27, VBLKSA			
Chloroethane	VBLKSA, VBLKPE, F6R26, F6R24, F6R27, F6R25			
Trichlorofluoromethane	F6R25, F6R26, F6R24, VBLKSA, VBLKPE, F6R27			
1,1-Dichloroethene	VBLKSA, F6R25, F6R24, VBLKPE, F6R27, F6R26			
1,1,2-Trichloro-1,2,2-Trifluoroethane	F6R26, F6R25, VBLKPE, VBLKSA, F6R24, F6R27			
Acetone	F6R24, VBLKPE, F6R27, F6R26, VBLKSA, F6R25			
Carbon disulfide	F6R24, VBLKPE, F6R26, VBLKSA, F6R25, F6R27			
Methyl acetate	F6R27, VBLKPE, F6R25, F6R24, VBLKSA, F6R26			
Methylene chloride	F6R25, F6R26, F6R24, F6R27, VBLKPE, VBLKSA			
trans-1,2-Dichloroethene	VBLKSA, VBLKPE, F6R25, F6R24, F6R26, F6R27			
Methyl tert-butyl ether	F6R25, VBLKPE, VBLKSA, F6R27, F6R24, F6R26			
1,1-Dichloroethane	VBLKPE, VBLKSA, F6R24, F6R26, F6R27, F6R25			
cis-1,2-Dichloroethene	F6R26, F6R27, F6R25, F6R24, VBLKSA, VBLKPE			
2-Butanone	VBLKPE, F6R27, F6R25, VBLKSA, F6R24, F6R26			
Bromochloromethane	VBLKSA, F6R27, F6R24, VBLKPE, F6R26, F6R25			
Chloroform	F6R26, VBLKPE, F6R24, VBLKSA, F6R25, F6R27			

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI **SDG: F6R18** Contract: EPW14035 Submission Group Id: 30115344 Lab Name: Shealy Environmental Services, Inc. Case: 45671 Client: EPA Region 6 SOW: SOM02.3

Test Name: EXES-1174

Defect Message: The following samples were analyzed after a highly contaminated sample and have no preceding instrument blank. Detects are not qualified. Nondetects are not qualified. Use professional judgement to qualify data.

Associated Samples: F6R24, F6R25, F6R26, F6R27, VBLKPE, VBLKSA				
1,1,1-Trichloroethane	F6R24, F6R25, VBLKSA, VBLKPE, F6R26, F6R27			
Cyclohexane	VBLKSA, F6R24, F6R25, F6R27, VBLKPE, F6R26			
Carbon tetrachloride	F6R25, F6R24, F6R27, VBLKPE, F6R26, VBLKSA			
Benzene	F6R26, F6R27, VBLKSA, F6R24, VBLKPE, F6R25			
1,2-Dichloroethane	F6R26, VBLKSA, VBLKPE, F6R25, F6R27, F6R24			
Trichloroethene	VBLKPE, F6R25, F6R26, VBLKSA, F6R27, F6R24			
Methylcyclohexane	VBLKSA, F6R25, VBLKPE, F6R26, F6R24, F6R27			
1,2-Dichloropropane	F6R27, F6R25, F6R24, F6R26, VBLKPE, VBLKSA			
Bromodichloromethane	VBLKSA, F6R26, F6R25, F6R24, VBLKPE, F6R27			
cis-1,3-Dichloropropene	F6R27, VBLKPE, F6R25, F6R26, VBLKSA, F6R24			
4-Methyl-2-pentanone	F6R25, VBLKSA, VBLKPE, F6R27, F6R26, F6R24			
Toluene	F6R25, VBLKPE, VBLKSA, F6R24, F6R26, F6R27			
trans-1,3-Dichloropropene	VBLKPE, F6R24, F6R26, F6R27, VBLKSA, F6R25			
1,1,2-Trichloroethane	F6R26, F6R25, F6R27, F6R24, VBLKPE, VBLKSA			
Tetrachloroethene	F6R24, F6R25, VBLKSA, F6R27, F6R26, VBLKPE			
2-Hexanone	VBLKSA, F6R27, F6R25, VBLKPE, F6R24, F6R26			
Dibromochloromethane	F6R26, VBLKPE, F6R27, F6R25, F6R24, VBLKSA			
1,2-Dibromoethane	F6R25, F6R26, VBLKSA, VBLKPE, F6R24, F6R27			
Chlorobenzene	F6R27, F6R25, F6R24, VBLKSA, F6R26, VBLKPE			
Ethylbenzene	F6R26, F6R27, VBLKSA, F6R24, VBLKPE, F6R25			
o-Xylene	VBLKPE, F6R27, F6R25, F6R24, F6R26, VBLKSA			
m, p-Xylene	VBLKSA, F6R26, F6R25, F6R24, VBLKPE, F6R27			
Styrene	F6R24, VBLKSA, F6R26, F6R27, VBLKPE, F6R25			
Bromoform	F6R24, VBLKPE, F6R26, F6R25, VBLKSA, F6R27			
Isopropylbenzene	F6R24, F6R26, VBLKSA, F6R25, F6R27, VBLKPE			
1,1,2,2-Tetrachloroethane	VBLKSA, F6R27, F6R24, F6R25, F6R26, VBLKPE			
1,3-Dichlorobenzene	F6R25, F6R26, VBLKSA, F6R27, VBLKPE, F6R24			
1,4-Dichlorobenzene	F6R25, F6R26, VBLKPE, F6R27, VBLKSA, F6R24			
1,2-Dichlorobenzene	F6R26, F6R24, F6R25, VBLKPE, VBLKSA, F6R27			
1,2-Dibromo-3-chloropropane	F6R24, F6R26, F6R27, VBLKSA, F6R25, VBLKPE			
1,2,4-Trichlorobenzene	VBLKPE, F6R27, F6R25, F6R24, VBLKSA, F6R26			
1,2,3-Trichlorobenzene	VBLKSA, F6R25, F6R27, F6R26, VBLKPE, F6R24			
1-Methyldecahydronaphthalene	F6R25			
1-Phenyl-1-butene	F6R25			
1H-Indene, 2,3-dihydro-1,2-dimethyl-	F6R24			
1H-Indene, 2,3-dihydro-1,6-dimethyl-	F6R24			
1H-Indene, 2,3-dihydro-4,6-dimethyl-	F6R24			

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI SDG: F6R18 Contract: EPW14035 Submission Group Id: 30115344

Lab Name: Shealy Environmental Services, Inc. Case: 45671 Client: EPA Region 6 SOW: SOM02.3

Test Name: EXES-1174

Defect Message: The following samples were analyzed after a highly contaminated sample and have no preceding instrument blank. Detects are not qualified. Nondetects are not qualified. Use professional judgement to qualify data.

Associated Samples: F6R24, F6R25, F	F6R26, F6R27, VBLKPE, VBLKSA
1H-Indene, 2,3-dihydro-5-methyl-	F6R24
2-Butene, 3-chloro-1-phenyl-, (Z)-	F6R26
2-Norbornanone, 1,3,7,7-tetramethyl-, ox	F6R27
Benzene, (1,2-dimethyl-1-propenyl)-	F6R24, F6R25
Benzene, (2-methyl-1-butenyl)-	F6R26
Benzene, 1,2,3,4-tetramethyl-	F6R24, F6R26
Benzene, 1,2,3-trimethyl-	F6R24
Benzene, 1,2,4,5-tetramethyl-	F6R24
Benzene, 1,3-diethyl-	F6R25
Benzene, 1,3-diethyl-5-methyl-	F6R24
Benzene, 1,4-diethyl-	F6R24
Benzene, 1-(1-methylethenyl)-2-(1-methyl	F6R26
Benzene, 1-ethyl-2,3-dimethyl-	F6R25, F6R24
Benzene, 1-ethyl-2,4-dimethyl-	F6R25, F6R24
Benzene, 1-ethyl-2-methyl-	F6R24
Benzene, 1-ethyl-3-methyl-	F6R24
Benzene, 1-methyl-3-propyl-	F6R24
Benzene, 1-methyl-4-propyl-	F6R24
Benzene, 2,4-diethyl-1-methyl-	F6R25
Benzene, 2-ethenyl-1,4-dimethyl-	F6R25
Benzene, 2-ethyl-1,4-dimethyl-	F6R24
Benzene, 4-ethyl-1,2-dimethyl-	F6R24
Decane	F6R24
Indan, 1-methyl-	F6R24
Naphthalene	F6R24
Naphthalene, 1,2,3,4-tetrahydro-1,1,6-tr	F6R27
Naphthalene, 1,2,3,4-tetrahydro-1-methyl	F6R24
Naphthalene, 1-methyl-	F6R24
Naphthalene, 2-methyl-	F6R24
Naphthalene, decahydro-2,6-dimethyl-	F6R27
Naphthalene, decahydro-2-methyl-	F6R26
Pentalene, octahydro-2-methyl-	F6R26
Unknown Alkane-01	F6R24, F6R26, F6R25
Unknown Alkane-02	F6R24, F6R25, F6R26
Unknown Alkane-03	F6R25, F6R24, F6R26
Unknown Alkane-04	F6R25, F6R24
Unknown-01	F6R25, F6R27, VBLKSA, F6R26, F6R24

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQISDG: F6R18Contract: EPW14035Submission Group Id: 30115344Lab Name: Shealy Environmental Services, Inc.Case: 45671Client: EPA Region 6SOW: SOM02.3

Toot	Mama	EXES-	1171
1 621	Name:		II/4

Defect Message: The following samples were analyzed after a highly contaminated sample and have no preceding instrument blank. Detects are not qualified. Nondetects are not qualified. Use professional judgement to qualify data.

Associated Sample	es: F6R24.	. F6R25.	. F6R26.	. F6R27	. VBLKPE	. VBLKSA

Associated Samples. Fuk23, Fuk23, 1	rukzu, rukz ⁷ , v deki e, v dekisa
Unknown-02	F6R25, F6R26, F6R27, F6R24
Unknown-03	F6R24, F6R27, F6R25, F6R26
Unknown-04	F6R24, F6R26, F6R27, F6R25
Unknown-05	F6R25, F6R24, F6R26, F6R27
Unknown-06	F6R26, F6R27, F6R25, F6R24
Unknown-07	F6R27, F6R25, F6R24, F6R26
Unknown-08	F6R27, F6R24, F6R25, F6R26
Unknown-09	F6R25, F6R27, F6R26
Unknown-10	F6R26, F6R25, F6R27
Unknown-11	F6R25, F6R27, F6R26
Unknown-12	F6R26, F6R25, F6R27
Unknown-13	F6R27, F6R25, F6R26
Unknown-14	F6R26, F6R25, F6R27
Unknown-15	F6R27, F6R26, F6R25
Unknown-16	F6R27, F6R26, F6R25
Unknown-17	F6R27, F6R26
Unknown-18	F6R26, F6R27
Unknown-19	F6R27, F6R26
Unknown-20	F6R27
Unknown-21	F6R27
Unknown-22	F6R27
Unknown-23	F6R27
Unknown-24	F6R27
Unknown-25	F6R27
o-Cymene	F6R24, F6R26, F6R25
p-Cymene	F6R24
trans,trans-1,6-Dimethylspiro[4.5]decane	F6R27
trans-Decalin, 2-methyl-	F6R25, F6R26

Method - Semivolatiles by SIM

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI	SDG: F6R18	Contract: EPW14035	Submission Group Id: 30115344
Lab Name: Shealy Environmental Services, Inc.	Case: 45671	Client: EPA Region 6	SOW: SOM02.3

Test Name: EXES-1104

Defect Message: The following samples have analyte results reported less than CRQLs. The associated method blank results are less than CRQLs. Detects are qualified U. Sample results have been reported at CRQLs.

Associated Samples: F6R20, F6R21, F6R27

Naphthalene	F6R20	
2-Methylnaphthalene	F6R27, F6R20, F6R21	

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI SDG: F6R18 Contract: EPW14035 Submission Group Id: 30115344

Lab Name: Shealy Environmental Services, Inc. Case: 45671 Client: EPA Region 6 SOW: SOM02.3

DMC_Surrogate

Method - Volatile Organics

Test Name: EXES-982

Defect Message: The following samples have DMC/surrogate percent recoveries greater than the primary maximum criteria Detects are qualified as estimated J+. Use professional judgment to qualify nondetects.

Associated Samples: F6R24, F6R25, F6R26, VIBLK60, VIBLK61, VIBLK62, VIBLK63

Chloroethane-d5	VIBLK63
1,1-Dichloroethene-d2	VIBLK62, VIBLK63, F6R25
2-Butanone-d5	VIBLK60, VIBLK61, VIBLK62
Chloroform-d	VIBLK60
Benzene-d6	F6R24
1,2-Dichloropropane-d6	F6R24, F6R26
Toluene-d8	F6R24
1,1,2,2-Tetrachloroethane-d2	F6R25, VIBLK61
1,2-Dichlorobenzene-d4	F6R25, F6R24

Method - Semivolatiles

Test Name: EXES-1346

Defect Message: The following samples have DMC/surrogate percent recoveries less than the primary minimum criteria. Detects are qualified as estimated J-.

Nondetects are qualified as estimated UJ.

Associated Samples: F6R23 F6R24

Abbotated Sumples: 1 Oktas, 1 Oktas		
Phenol-d5	F6R23	
4-Methylphenol-d8	F6R23	
Nitrobenzene-d5	F6R23	
2-Nitrophenol-d4	F6R23	
2,4-Dichlorophenol-d3	F6R23	
4,6-Dinitro-2-methylphenol-d2	F6R24	

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI SDG: F6R18 Contract: EPW14035 Submission Group Id: 30115344

Lab Name: Shealy Environmental Services, Inc. Case: 45671 Client: EPA Region 6 SOW: SOM02.3

Test Name: EXES-787

Defect Message: The following samples have DMC/surrogate percent recoveries less than the expanded minimum criteria. Detects are qualified as estimated J-.

Nondetects are qualified as unusable R.

Associated Samples: F6R23

Associated Samples: FoR25		
1,4-Dioxane-d8	F6R23	
2-Chlorophenol-d4	F6R23	

Test Name: EXES-973

Defect Message: The following method blanks have DMC/surrogate percent recoveries outside criteria. Detects are not qualified. Nondetects are not qualified. Use professional judgment to qualify data.

Associated Samples: SBLK12

1,4-Dioxane-d8	SBLK12

Test Name: EXES-982

Defect Message: The following samples have DMC/surrogate percent recoveries greater than the primary maximum criteria Detects are qualified as estimated J+. Use professional judgment to qualify nondetects.

Associated Samples: F6R23, F6R24, F6R25, F6R26

4-Chloroaniline-d4	F6R24, F6R25, F6R26, F6R23	
4-Nitrophenol-d4	F6R25, F6R26, F6R23	
4,6-Dinitro-2-methylphenol-d2	F6R23	

Method - Semivolatiles by SIM

Test Name: EXES-787

Defect Message: The following samples have DMC/surrogate percent recoveries less than the expanded minimum criteria. Detects are qualified as estimated J-.

Nondetects are qualified as unusable R.

Associated Samples: F6R23, F6R23RX, F6R24, F6R25, F6R26, F6R27

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI	SDG: F6R18	Contract: EPW14035	Submission Group Id: 30115344
Lab Name: Shealy Environmental Services, Inc.	Case: 45671	Client: EPA Region 6	SOW: SOM02.3

Test Name: EXES-787

Defect Message: The following samples have DMC/surrogate percent recoveries less than the expanded minimum criteria. Detects are qualified as estimated J-.

Nondetects are qualified as unusable R.

Associated Samples: F6R23, F6R23RX, F6R24, F6R25, F6R26, F6R27

Associated Sumples: 1 Oktasiki, 1 Oktas, 1 Oktas, 1 Oktas		
Fluoranthene-d10	F6R24, F6R23, F6R26, F6R25	
2-Methylnaphthalene-d10	F6R23RX, F6R26, F6R24, F6R23, F6R27, F6R25	

Test Name: EXES-982

Defect Message: The following samples have DMC/surrogate percent recoveries greater than the primary maximum criteria Detects are qualified as estimated J+. Use professional judgment to qualify nondetects.

Associated Samples: F6R20, F6R23RX, F6R24RX, F6R26RX, F6R27

Fluoranthene-d10	F6R27, F6R20, F6R26RX, F6R24RX, F6R23RX	
2-Methylnaphthalene-d10	F6R20, F6R26RX, F6R24RX	

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI	SDG: F6R18	Contract: EPW14035	Submission Group Id: 30115344
Lab Name: Shealy Environmental Services, Inc.	Case: 45671	Client: EPA Region 6	SOW: SOM02.3

MatrixSpikes

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI SDG: F6R18 Contract: EPW14035 Submission Group Id: 30115344

Lab Name: Shealy Environmental Services, Inc. Case: 45671 Client: EPA Region 6 SOW: SOM02.3

InternalStandard

Method - Semivolatiles

Test Name: EXES-1524

Defect Message: The following samples have internal standard area response greater than maximum criteria. Detected compounds are qualified estimated J-.

Nondetects are not qualified.

Associated Samples: F6R23, F6R25, F6R26

Naphthalene-d8 F6R26, F6R23, F6R25

Method - Semivolatiles by SIM

Test Name: EXES-1524

Defect Message: The following samples have internal standard area response greater than maximum criteria. Detected compounds are qualified estimated J-.

Nondetects are not qualified.

Associated Samples: F6R23, F6R24, F6R25, F6R26

Naphthalene-d8	F6R26, F6R24	
Acenaphthene-d10	F6R23, F6R26, F6R25, F6R24	
Phenanthrene-d10	F6R25, F6R24, F6R26	
Chrysene-d12	F6R26, F6R24, F6R25, F6R23	

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI	SDG: F6R18	Contract: EPW14035	Submission Group Id: 30115344
Lab Name: Shealy Environmental Services, Inc.	Case: 45671	Client: EPA Region 6	SOW: SOM02.3

PercentSolids

Tue, 5 Jan 2016 10:51:29

Data Validation Report

Data Review Results

Lab Code: EQI

Lab Name: Shealy Environmental Services, Inc.

Duta Review Results		
SDG: F6R18	Contract: EPW14035	Submission Group Id: 30115344
Case: 45671	Client: EPA Region 6	SOW: SOM02.3

SampleAnalysis

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI SDG: F6R18 Contract: EPW14035 Submission Group Id: 30115344

Lab Name: Shealy Environmental Services, Inc. Case: 45671 Client: EPA Region 6 SOW: SOM02.3

DetectionLimit

Method - Semivolatiles

Test Name: EXES-790

Defect Message: The following samples have analyte results greater than or equal to detection limit (MDL) and below quantitation limit (CRQL). Detects are qualified as estimated J.

Associated Samples: F6R20, F6R21, F6R23, F6R24, F6R25, F6R26

Phenol	F6R21, F6R20
Naphthalene	F6R23, F6R26, F6R24
2-Methylnaphthalene	F6R26, F6R25
Acenaphthene	F6R23
Phenanthrene	F6R26, F6R24, F6R25
Anthracene	F6R24, F6R23
Pyrene	F6R23
Benzo(a)anthracene	F6R23
Chrysene	F6R24, F6R23

Method - Semivolatiles by SIM

Test Name: EXES-790

Defect Message: The following samples have analyte results greater than or equal to detection limit (MDL) and below quantitation limit (CRQL). Detects are qualified as estimated J.

Associated Samples: F6R20, F6R21, F6R23RX, F6R24, F6R25, F6R26, F6R26RX, F6R27, SBLK13

11880 0140 0 84111 91080 1 01120)	11550 VIII VIII VIII VIII VIII VIII VIII V		
Naphthalene	F6R20, SBLK13		
2-Methylnaphthalene	F6R21, F6R27, F6R20, SBLK13		
Anthracene	F6R26RX		
Fluoranthene	F6R26RX		
Pyrene	F6R26RX		
Chrysene	F6R26RX		
Benzo(k)fluoranthene	F6R26, F6R25		

Data Review Results

Tue, 5 Jan 2016 10:51:29

Lab Code: EQI	SDG: F6R18	Contract: EPW14035	Submission Group Id: 30115344
Lab Name: Shealy Environmental Services, Inc.	Case: 45671	Client: EPA Region 6	SOW: SOM02.3

Test Name: EXES-790

 $\textbf{Defect Message: The following samples have analyte results greater than or equal to detection limit (MDL) and below quantitation limit (CRQL). \ \textbf{Detects are qualified}$

as estimated J.

Associated Samples: F6R20, F6R21, F6R23RX, F6R24, F6R25, F6R26, F6R26RX, F6R27, SBLK13

Benzo(a)pyrene	F6R26
Indeno(1,2,3-cd)pyrene	F6R23RX, F6R25
Dibenzo(a,h)anthracene	F6R23RX, F6R24
Benzo(g,h,i)perylene	F6R23RX, F6R26, F6R25, F6R26RX